

5.6 Commands Listed by Keyboard code

Key	Function	arg			
Alt F1	EXECUTE	s	Ctrl F1	WAVE__CAL	l
Alt F2	REPAINT	-	Ctrl F2	DYNO__OPTS	-
Alt F3	TOGL__ANG__LD	-	Ctrl F3	unused	-
Alt F4	HOME__ALL	c	Ctrl F4	TOGL__SLIT__AUX	c
Alt F5	GOTO__SLIT	r	Ctrl F5	SERVO__SET	r
Alt F6	GOTO__WAVE	r	Ctrl F6	DY__SV__OPTS	-
Alt F7	TOGL__OPLV__AUX	c	Ctrl F7	TEMP__OPTS	-
Alt F8	TOGL__DYNO__AUX	c	Ctrl F8		-
Alt F9	TOGL__ETST__MD	-	Ctrl F9		-
Alt F10	TOGL__SCAN	c	Ctrl F10		-
Alt A	ANTILOG	r	Ctrl D	QUIT	c
Alt B	BASELINE	-	Ctrl END	TOGL__XLINK__MD	-
Alt C	CORRECT	-	Ctrl HOME	FIT__XY	-
Alt D	REMOVE	c	Ctrl LEFT	PRINT__FILE	-
Alt E	WEIGHT	s	Ctrl PGDN	DEMOD__OPTS	-
Alt F	FLIP	-	Ctrl PGUP	TOGL__ER__FLGS	-
Alt G	SHOW__DATA	s	Ctrl RIGHT	TM__SV__OPTS	-
Alt H	HELP	-			
Alt I	SMOOTH	-	F1	SET__BANDW	r
Alt J	PEAK__PICK	-	F2	TOGL__AU__MD	-
Alt K	ENTER__KINET	-	F3	SET__STEP	r
Alt L	LOAD__FILE	s	F4	TOGL__OFST__MD	-
Alt M	MULTIPLY	r	F5	TOGL__BW__MD	-
Alt N	NOTE	t	F6	MAKE__SETUP	-
Alt O	OFFSET	r	F7	SET__TIMC	r
Alt P	ADD	s	F8	NAME__OPTS	-
Alt Q	SUBTRACT	s	F9		-
Alt R	RENAME	s	F10		-
Alt S	SAVE__FILE	c			
Alt T	ENTER__TEMP	-	Shift F1	SET__TEMP	r
Alt U	LOG	r	Shift F2	SET__EQUIL	r
Alt V	INVERSE	r	Shift F3	TOGL__TEMP__MD	-
Alt W	ENTER__WAVE	-	Shift F4	TOGL__TEMP__AUX	c
Alt X	OVERLAY__VIEW	s	Shift F5	REPT__OPTS	-
Alt Y	Y__LABEL	s	Shift F6	SET__REPS	i
Alt Z	OVERLAY__DATA	s	Shift F7	TOGL__REP	c
Alt 1	EXTRACT	-	Shift F8	DEFAULT__DRIVE	s
Alt 2	STATS	-	Shift F9	DIRECTORY	-
Alt 3	TOGL__X__NEXT	-	Shift F10	TOGL__EXTN__AUX	c
Alt 4	POLY__OPTS	-			
Alt 5	DIVIDE	r	DOWN	SET__LOWER	r
Alt 6	RATIO	s	END	FIT__Y	-
Alt 7	SMOO__OPTS	-	HOME	REPLOT	-
Alt 8	PEAK__OPTS	-	LEFT	SET__LEFT	r
Alt 9	TOGL__ALL__PTS	-	PGDN	PRIOR	-
Alt 0	TOGL__ZERO__MD	-	PGUP	NEXT	-
Alt DASH	NOTE__FULL	t	RIGHT	SET__RIGHT	r
Alt EQUAL	TOGL__FULL__SCR	-	UP	SET__UPPER	r